

Seismic evaluation of the existing RC buildings in Japan

June 2017

**Building Research Institute,
Japan**

Matsutaro SEKI

Contents

- 1. Earthquake damage and Japanese seismic code**
- 2. Seismic evaluation of existing buildings**
- 3. Post earthquake quick inspection of damaged buildings**
- 4. Conclusions**

Earthquake damage and Japanese seismic code

1995 Hyogoken Nanbu (Kobe) earthquake, Japan



兵庫県南部地震、1995.1.1

Disaster Risk in the World


Disaster Risk in Japan is highest in the World:
Tokyo, Osaka



Recent Big Earthquakes higher than M.8 in the World (2010)

世界の震源分布 (2010年版)

東京大学 地震研究所




ERI, Univ. of Tokyo

マグニチュードは理科年表による

Casualties by Earthquakes in the World

(1990-2008.8)




Nakano (IIS, U-Tokyo)

犠牲者の統計(世界).xls

Earthquake Around Japan Island (1900-2017)

今世紀に日本周辺で起きた主な地震



(『朝日新聞』1995年1月25日)

Kanto Earthquake, 1923

Reinforced Concrete Building



<http://research.kahaku.go.jp/rikou/namazu/03kanto/marunouti/marunouti.html>

Kanto Earthquake, 1923



Damage of Masonry Building

<http://research.kahaku.go.jp/rikou/namazu/03kanto/marunouti/marunouti.html>

Seki M., UTCB Lecture note, May 2017, BRI, Japan

Lessons from Kanto Earthquake, 1924

1. Horizontal seismic intensity: 0.1 was adopted for seismic design.
2. Damage of reinforced concrete buildings was small.
3. Damage of masonry buildings was big.
4. Discussion on the benefit of rigid structure and flexible structure was done. From then, the rigid structure was recommended.

Dynamic Time History Analysis and Super High Rise Buildings

1. In 1960, Computer was used for dynamic analysis.
2. Many Earthquake ground motions were recorded.
3. in 1968, the first high rise building was completed.
(H=147m, 36F, Steel structure)



Tokachi-oki Earthquake, 1968

Shear Failure of Column (Brittle failure)



**Hachinohe
Technical High
School**

Photo; Tsuneo Okada


Lessons from Tokachi-oki Earthquake, 1968

1. There are lots of Shear Failure of RC Column
2. Lots of research works on Shear Failure were done from then.
3. Japanese seismic code was revised in 1971.
4. Hoop space was changed from 30 cm to 10 cm.
5. Seismic design was changed from shear failure to flexural failure.

Lessons from Tokachi-oki Earthquake, 1968

AIJ Journal. January 1969

Load Deflection Curves of Various type Structures



Japanese New Seismic Code (Required Horizontal Strength)

- 1977: Draft of New Seismic Code

- 1981: Issue of New Seismic Code

- ◆ **Characteristics**

1. **Design force is calculated by linear response spectrum.**
2. **Required design strength can be reduced Based on the Ductility of Structure.**

Basic Concept of Japanese Required Horizontal Strength

Required horizontal strength (Q_{un})

$$C = Q_{un}/W = C_o \cdot R_t \cdot D_s \cdot F_{es}$$


C_o : Standard shear coefficient ≥ 1.0

R_t : Design spectral factor ≤ 1.0

D_s : Structural characteristic factor ≥ 0.25 (RC: ≥ 0.30)

F_{es} : Shape factor ≥ 1.0

W : Weight of building





Based on the energy constant theory after Newmark

Prediction of nonlinear response displacement

$$C_o = C \times \sqrt{2\mu - 1}$$

Transition of Japanese Seismic Code

1968 Tokachi oki Earth.	Old code	1971 Revised: Japanese seismic code	Allowable design
1978 Miyagiken oki Earth.			
1995 Kobe Earth.	Shifting	1981 Revised: Japanese seismic code (New Seismic Code)	Ductility of Column
	New code		2 steps design: (1) Small Earth. (2) Strong Earth.



Hyogoken Nanbu Earthquake, January 1995



Column Designed by the Old Code



Column Designed by the New Code

Hyogoken Nanbu Earthquake, January 1995



Hyogoken Nanbu Earthquake, January 1995



First Story Collapsed (designed by old code)

Hyogoken Nanbu Earthquake, January 1995




Hyogoken Nanbu Earthquake, January 1995



Building collapsed on the Road

<http://www.kobe-c.ed.jp/shizen/strata/quake/photo/index2.html>

Hyogoken Nanbu Earthquake, January 1995



Hyogoken Nanbu Earthquake, January 1995



Top of the Piles were Damaged

Hyogoken Nanbu Earthquake, January 1995



Residential House (New Code)



Failure of First Story (New Code)

被災した集合住宅・テツアドー出版1995

Hyogoken Nanbu Earthquake, January 1995



Cracks of Beam Column Joint (New Code)



Failure of Beam (New Code)

Hyogoken Nanbu Earthquake, January 1995



Hyogoken Nanbu Earthquake, January 1995




Fall of Precast Concrete Panels

Hyogoken Nanbu Earthquake, January 1995

Conclusions(1)


Construction year ad Damage of buildings



神戸市中央区JR三宮駅付近の悉皆調査(923棟)

出典:平成7年阪神・淡路大震災建築震災調査委員会中間報告

Hyogoken Nanbu Earthquake, January 1995



Hyogoken Nanbu Earthquake, January 1995

Conclusions(2)

1. Lot of severe damaged buildings before 1980 code
2. Small number of damaged buildings after 1981 code. Small modification of 1981 seismic code was done.
3. If Seismic strengthening has been performed, there is little damage.

Tohoku Taiheiyo Earthquake, 3.11,2011

Story Collapse (Old Seismic Code)



Photo: Fukuyama H.

Tohoku Taiheiyo Earthquake, 3.11,2011

Photo: Fukuyama H. ,BRI



Tohoku Taiheiyo Earthquake, 3.11,2011

東日本大震災；サンデー毎日増刊4月2日号



Damaged detached timer house by Tsunami

Tohoku Taiheiyo Earthquake, 3.11,2011



Liquefaction

BRI report

Sliding of Soil



JAAF, June 2011



Tohoku Taiheiyo Earthquake, 3.11,2011

Fall of the Ceiling


BRI report



Tohoku Taiheiyo Earthquake, 3.11, 2011

Furumura, Takemura; ERI., Univ. of Tokyo



Observed strong ground motions




Long Duration Ground Motion (about 100 seconds)

Tohoku Taiheiyo Earthquake, 3.11,2011

Velocity time history and Velocity response spectrum



Furumura, ERI. Univ. of Tokyo



Predominant Periods of Ground Motions

Tohoku Taiheiyo Earthquake, 3.11,2011

Conclusions (1)

RC buildings

- 1. The Buildings constructed by 1980 old code were severely damaged but not so many buildings.**
- 2. The retrofitted buildings showed the good performance.**
- 3. The buildings constructed by 1981 new code were almost safe but small modification was performed.**

Tohoku Taiheiyo Earthquake, 3.11,2011

Conclusions (2)

4. Other damages

- ① **Serious Damage of non structural members**
- ② **Liquefaction of soil occurred and detached house suffered severely damaged.**
- ③ **The high rise buildings were affected by the long period dominated ground motion.**
- ④ **Tsunami did great damage to the lots of houses.**

History of Seismic Evaluation Standard in Japan

1. Research work on seismic retrofit has started after 1968 Tokachi-oki earthquake
2. In 1977 seismic evaluation standard was issued by JBPA . It was only used for disaster mitigation in Shizuoka Prefecture, Japan
3. It was legislated as “**Act for Promotion of Renovation for Earthquake- Resistant Structures of Buildings**” just after 1995 Hyougoken Nanbu earthquake.
4. 2005: Revision of the Act; Enforcement of promotion
5. 2013: Revision of the Act; Mandatory for the special –use building

2001 Revised version

Standard for Seismic Evaluation of Existing Reinforced Concrete Buildings, 2001

2001

**The Japan Building Disaster
Prevention Agency (JBDPA)**



JBDPA seminar note

Basic Policy

JBDPA Seminar PPT

- Seismic Evaluation=In-situ investigation
+Calculation
- Digitization of Capacity
 1. Seismic Index of Structure : I_s
 2. Seismic Index of Non Structural Element: I_N
- Judgement comparing Seismic Demand
Index of Structure

JBDPA seminar note

Flow from Seismic Evaluation to Seismic Retrofit

(1) Seismic Index : I_s

(2) Seismic Demand Index: I_{so}

- $I_s \geq I_{so}$: OK -----> END
- $I_s < I_{so}$: Retrofit -----> GO TO (3)

(3) Select of Retrofitting Methods

(4) Structural Design of Retrofit

(5) Judgment of Retrofitted Building

- $I_s \geq I_{so}$: OK

Seismic Estimation Level

- 1st level evaluation (Failure of wall & column)
 - The simplest calculation. Strength of column and wall is calculated by section area and material strength.
- 2nd level evaluation (Failure of wall & column)
 - C index and F index of column and wall are calculated by member size, material, rebar, concrete, etc. Slab and beam are not considered in the estimation.
- 3rd level evaluation (Failure of beam)
 - The most complicated calculation. Beam and slab are considered in the estimation.

Material Property required for Seismic Evaluation

short ← Calculation time → long


		1st	2nd	3rd
Size of Members	Column, Wall	○	○	○
	Beam			○
Strength of Members	Concrete	○	○	○
	Rebar		○	○
Location of rebar			○	○

Column, Wall ———→ |


Column, Wall + Beam ———→ |

JBDPA seminar note

Failure Type




Column failure type




Beam failure type

Failure Type




Column failure type



Beam failure type



Example of column failure type



**1968 Tokachi-oki
Earth. (Hachinohe
Technical High
School)**



Example of Beam failure type





1985 Mexico Earthquake

Photo: Tsuneo Okada

JBDPA seminar note

Example of Beam failure type



Breaking of rebar

Photo: Tsuneo Okada

1985 Mexico Earthquake



1995 Kobe Earthquake

Nishinomiya Junior High School

Photo: Kitayama



Compressive crash of column

2004 Niigata Chuetsu Earth.

Photo: Yoshiaki Nakano



Shear failure of column


Focal points of the Standard

- Objective of seismic evaluation
 1. Digitization of seismic capacity
 2. Grasp of the failure process of structural members



Importance of the appropriate analytical modeling of structure

Importance of In-situ investigation



The Seismic index of structure (I_s)

$$I_s = E_o S_D T \quad (1)$$

I_s : Seismic index of structure


E_o : Basic seismic index of structure

S_D : Irregularity index

T : Time index

S_D index


Collapse (Soft Story Mechanism)




JBDPA seminar note

S_D index

Torsional vibration




1978 Miyagiken-oki EQ.



Torsional vibration

JBDPA seminar note


1978 Miyagiken-oki EQ.



Torsional vibration

JBDPA seminar note

Load vs. Displacement



Basic seismic index (Eo)

Basic seismic index: E_0

$$E_0 = \frac{n+1}{n+i} \sqrt{E_1^2 + E_2^2 + E_3^2}$$


Eq. (4)

$$E_0 = \frac{n+1}{n+i} \left(C_1 + \sum_j \alpha_j C_j \right) \cdot F_1$$

Eq. (5)

α_j : Effective strength factor

α_j : Effective strength factor



JBDPA seminar note


Basic seismic index E_o

$$I_s = E_o \times S_D \times T$$
$$E_o = C \times F$$

- Basic seismic index: E_o

$$E_o = C [\text{strength index}] \times F [\text{ductility index}]$$

$$\text{cf. } C_e = C_y \times \sqrt{2\mu - 1}$$



Newmark:
Energy constant theory

JBDPA seminar note

Japanese Seismic Design & Seismic Index (Is, Iso)

$$C_E \leq C_Y \times \sqrt{2\mu - 1}$$

Seismic Design

Demand
Capacity
(Ex. 1.0)

Yield Strength
(Ds)
0.3

Ductility Factor
(μ)
6.0)

**Seismic
Evaluation**

Demand Index
(Iso)
(Ex. 0.6)


Strength Index
(C)
0.3

Ductility Index
(F)
2.0)

Basic Seismic Index: $E_o = C \times F$

Seismic Index : $I_s = E_o \times S_D \times T$


E_o index (1) **One type of member**



$$I_s = E_o \times S_D \times T$$
$$E_o = C \times F$$


$$E_o \text{ index of Building-1: } E_{o1}(1) = C_1 \times F_1$$

Ductility




JBDPA seminar note

Ductility




JBDPA seminar note

Shear failure of short column



E₀ index (2) **Two types of members**



Q . E_0 index of the building???

E₀ index (3) Two types of members


Q: E₀ index of the building? ? ?

E₀ = C₁ x F₁ or C₂ x F₂ [= E₀₁ or E₀₂] : under estimate

E₀ = (C₁ x F₁) + (C₂ x F₂) [=E₀₁ + E₀₂] : over estimate




A: E₀ = $\sqrt{(C_1 \times F_1)^2 + (C_2 \times F_2)^2}$



JBDPA seminar note

E₀ index (4) Local failure vs. safety



- $E_{0A} = (C_1 + \alpha C_2) \times F_1$
- $E_{0B} = \sqrt{(C_1 \times F_1)^2 + (C_2 \times F_2)^2}$

α : Strength effective factor

Allowable of failure of member-1

Not allowable

$$\rightarrow E_0 = \max (E_{0A} , E_{0B})$$

$$\rightarrow E_0 = E_{0A}$$

JBDPA seminar note

Seismic demand index

$$I_s \geq I_{so} \quad (37)$$

$$I_{so} = E_s \cdot Z \cdot G \cdot U \quad (38)$$

$$C_{TU} S_D \geq 0.3 \cdot Z \cdot G \cdot U \quad (39)$$

C_{TU} : Cumulative strength index at ultimate deformation

S_D : Irregularity index

E_s : Basic demand index $E_{s1} = 0.8$, $E_{s2,3} = 0.6$

Z : Zone index, G : Ground index, U : Usage index

Seismic demand index

1st level estimation $I_{so} = 0.8$ ($Z G U = 1.0$)

1968 Tokachi-oki EQ

2nd level estimation $I_{so} = 0.6$ ($Z G U = 1.0$)


1968 Tokachi-oki EQ, 1978 Miyagiken-oki EQ, etc.

Not deterministic (Damage ratio: about 10%)

$CTU S_D \geq 0.3 Z G U$


Correspond to D_s (Japanese seismic code)

Damage ratio due to the strong earthquake in Japan



JBDPA seminar note

Damage ratio due to 1995 Kobe EQ



AIJ report

JBDPA seminar note

Is index doesn't directly cover the following items;

1. Usability after earthquake

Is it possible to keep using or not?

2. Repairability after damaged

Does the capacity recover rapidly after repairing or not?

3. Durability in the future

Is it possible to keep using and safety in the future or not?



The investigator should inform them to the owner of buildings.

Post Earthquake Quick Inspection of Damaged Buildings (Reinforced concrete buildings)

The content of this document is quoted from Manual of Postearthquake Quick Inspection of Damaged Building, Japan Building Disaster Prevention Association (JBDPA), Japan Council for Quick Inspection of Earthquake Damaged Building, January 1998, and the Brochure for Postearthquake Quick Inspection of Damaged Buildings, Japan Council for Quick Inspection of Earthquake Damaged Buildings, December 2001.

February 2011

Japan Building Disaster Prevention Association

Matsutaro Seki

I. Outline of Postearthquake Quick Inspection of Damaged Buildings

1. What is the postearthquake quick inspection of damaged buildings?

◆ The aim of the quick inspection is to prevent the secondary disaster, regarding the life of people by inspection of damaged building through the evaluation of risk for collapse of building, fall of window glass and exterior walls and overturn of building equipments that may be occurred by the aftershocks.


◆ The placards evaluated should be put clearly on the building. This placards system informs the predicted risk of building to the owners and the pedestrians.

◆ The evaluated placards are classified into three categories; “Inspected”, “Limited Entry” and “Unsafe”.

2. Who is responsible for the safety management of damaged buildings?

◆ Generally the **owners** and **managers** are responsible for keeping the buildings safe.

◆ **Municipality** carry out the quick inspection as the part of its emergent measures just after the earthquake. **Prefectural government** must support the activities of municipality.





Inspectors

応急危険度判定結果

調査済

INSPECTED

◆この建築物の被災程度は小さいと考えられます
◆建築物は使用可能です

建築物名称

注記：

整理番号

判定日時 月 日 午前・午後 時現在

災害対策本部 電話

応急危険度判定結果

要注意

LIMITED ENTRY

◆この建築物に立ち入る場合は十分注意して下さい
◆応急的に補修する場合には専門家に相談下さい

建築物名称

注記：

整理番号

判定日時 月 日 午前・午後 時現在

災害対策本部 電話

応急危険度判定結果

危険

UNSAFE

◆この建築物に立ち入ることは危険です
◆立ち入る場合は専門家に相談し、応急措置を行う
必要があるして下さい

建築物名称

注記：

整理番号

判定日時 月 日 午前・午後 時現在


災害対策本部 電話

Evaluated Placards




Standard for Damage Rate Inspection, Japan
Building Disaster Prevention Association, Jan.
2001 (in Japanese)

Seki M., UTCB Lecture note, May 2017, BRI, Japan




General Flow of Quick Inspection, Damage Rate Inspection and Rehabilitation in Japan (Manual, Standard, Guide line)

II. Manual of Postearthquake Quick Inspection of Damaged Building



Manual of Postearthquake Quick Inspection, Japan Building Disaster Prevention Association, Jan., 1998(in Japanese)



Quick Inspection Training

**Carried out on 16th, February in Talca,
Chile by JICA program**

Two Buildings

① Public Office Building

② School Building



Seki M., UTCB Lecture note, May 2017, BRI, Japan

[Complement for Quick Inspection]

Feb. 16 / 2011

Seki




~~Damage of Column~~
<Inspection 2>

Judgment (1) ~~for~~

① • Damage Rank > III ?

Small cracks:
Crack Width $\leq 2\text{mm}$


Rank III




Beam-Column Joint

Judgment (2)


(2)



(3)



(4)




< Damage of Column >


- Most serious damage floor, \rightarrow (F.)
(and. Direction)

⑤ Damage Rank IV ?

- NO. Settlement of Floor




• Damage Ratio =
$$\frac{\text{Number of Damage Columns}}{\text{Number of Inspected Columns}}$$



< Example >

• Inspection Direction (x)



• Inspection Ratio

$$= \frac{8}{13} = 0.61 \rightarrow 61\% > 50\% \rightarrow \text{OK!}$$

• Damage Ratio for RANK V (⑤)

$$= \frac{1}{8} = 0.12 \rightarrow 12\% \rightarrow \text{RANK C}$$

• Damage Ratio for RANK IV (④)

$$= \frac{2}{8} = 0.25 \rightarrow 25\% \rightarrow \text{RANK C}$$


Note: Plan section is desirable before Inspection.

If not, Inspectors have to draw.


• Generally, we don't have any structural drawings just after the earthquake.

◀ Inspection 3 ▶ (falling and shifting of object)


① Frame and glass of window




③ Exterior finishing material (Dry construction)




② Exterior finishing material (Wet construction)



④ Signboard and fitting, Water tank, etc.



⑤ Exterior Escape stair





Seki M., UTCB Lecture note, May 2017, BRI, Japan



Seki M., UTCB Lecture note, May 2017, BRI, Japan



Seki M., UTCB Lecture note, May 2017, BRI, Japan



Seki M., UTCB Lecture note, May 2017, BRI, Japan




Table 3.2.2-1 Quick Inspection Sheet for Reinforced Concrete Buildings and Steel Framed Reinforced Concrete Buildings⁽¹⁾

Serial No. _____ Inspection date and hour 16th Feb. 2011 Time of Inspection _____
 Name of the Inspector (county and prefecture / No.) _____
 Outline of the building Public Office
 1 Name of the building School 1.1 Building No. _____
 2 Address of the building _____ 2.1 Serial No. in the residential district map _____
 3 Use 1. Detached house 2. Tenement style 3. Apartment house 4. Dwelling house combined with other uses 5. Store 6. Office 7. Inn and Hotel 8. Public facilities such as a government building 9. Hospital and clinic 10. Day nursery 11. Factory 12. Warehouse 13. School 14. Gymnasium 15. Theater, amusement facilities 16. Others ()
 4 Type of Structure Reinforced concrete 2. Pre-cast concrete 3. Concrete block 4. Steel framed reinforced concrete 5. Hybrid of () and ()
 5 Number of stories Above ground 1 and underground _____
 6 Size of the building Dimensions of the first floor _____ m × _____ m

Inspection Inspection method: (1. Appearance inspection only) (2. Appearance and internal visual inspection)
 Inspection 1 The degree of danger judged at a glance (mark the appropriate items with a circle, judge the building to be dangerous, stop the inspection and skip to the comprehensive judgment).
 1. Entire or partial collapse and fallen floors of the building 2. Significant destruction of the foundation and its significant displacement from the superstructure
 3. Significant inclination of the building in whole or in part 4. Others ()

Inspection 2 The degree of danger judged from the states of the adjacent buildings, the nearby ground, the building frames and other factors

Judgment (1)	Rank A	Rank B	Rank C
① Whether there are members that suffered damage severer than damage level III	1. No	2. Yes	
Judgment (2)			
② Presence of danger caused by destruction of the adjacent buildings and the nearby ground	1. No	2. Uncertain	3. Yes
③ Settlement of the entire building due to destruction of the ground	1. Less than 0.2 m	2. 0.2 m - 1.0 m	3. More than 1.0 m
④ Inclination of the entire building due to differential settlement	1. Less than 1/60	2. 1/60 - 1/30	3. More than 1/30
Damage to columns (the floor (which suffered the most serious damage) through the inspecting for ⑤ and ⑥ below () (if bearing wall structure is in use, the length of the wall is substituted for the number of columns))			
⑤ Number of columns that suffered damage level V () / Number of columns inspected () (Inspection rate () %)	1. Less than 1%	2. 1% - 10%	3. More than 10%
⑥ Number of columns that suffered damage level IV () / Number of columns inspected () (Inspection rate () %)	1. Less than 10%	2. 10% - 20%	3. More than 20%
Judgment (2)	1. Inspected (when all items are given Rank A)	2. Limited entry (when one of the items is given Rank B)	3. Unsafe (when one or more items are given Rank C, or when two or more items are given Rank B)

Judgment of the degree of danger
 Judgment is determined by judgment (1) or judgment (2), whichever is greater

Judgment of the degree of danger	Rank A	Rank B	Rank C
① Frame and glass of the window	1. Almost no damage	2. Deformation and cracks	3. Danger of falling
② Exterior finishing material (for wet construction)	1. Almost no damage	2. Partial cracking and crevices	3. Significant cracking and spalling
③ Exterior finishing material (for dry construction)	1. Slight damage such as cracks in the joint	2. Crevices observed in the plate	3. Significant displacement of the joint and destruction of the plate
④ Signboard and fitting	1. No tilt	2. A slight tilt	3. Danger of falling
⑤ Exterior escape stair	1. No tilt	2. A slight tilt	3. A significant tilt
⑥ Others ()	1. Safe	2. Special attention required	3. Dangerous
Judgment of the degree of danger	1. Inspected (when all items are given Rank A)	2. Limited entry (when one or more item is given Rank B)	3. Unsafe (when one or more item is given Rank C)

Comprehensive judgment (the building should be judged here to be dangerous if it was judged to be dangerous in Inspection 1; otherwise it should be judged according to the degree of danger in Inspection 2 or in Inspection 3, whichever is greater).
 1. Inspected (green) 2. Limited entry (yellow) 3. Unsafe (red)
 Comment (state whether danger is from the building frame, or from falling objects)

Total column should be filled in with figures

RC

Serial No. _____
 Building No. _____
 Serial No. in the residential district map _____
 3 _____
 4 _____
 Above ground _____ stories
 Under-ground _____ stories
 a _____ m
 b _____ m

Inspection method

1 _____

Judgment (1)

② _____

③ _____

④ _____

The most seriously damaged floor

⑤ _____

⑥ _____

Judgment (2)

Judgment

① _____

② _____

③ _____

④ _____

⑤ _____

⑥ _____

Judgment

Comprehensive judgment



Seki M., UTCB Lecture note, May 2017, BRI, Japan



Seki M., UTCB Lecture note, May 2017, BRI, Japan



Seki M., UTCB Lecture note, May 2017, BRI, Japan



Seki M., UTCB Lecture note, May 2017, BRI, Japan

1st

Total Number: 34

Rank IV : 3

V : 3

$$3/34 =$$

$$3/34 =$$

$$0.088 \quad 88\%$$

$$0.088 \quad 88\%$$




Table 3.2.2-1 Quick Inspection Sheet for Reinforced Concrete Buildings and Steel Framed Reinforced Concrete Buildings⁽¹⁾

Serial No. _____ Inspection date and hour 16th Feb. 2011 Time of Inspection _____
Name of the Inspector (county and prefecture / No.) _____

Outline of the building

- 1 Name of the building School 1.1 Building No. _____
2 Address of the building _____ 2.1 Serial No. in the residential district map _____
3 Use 1. Detached house 2. Tenement style 3. Apartment house 4. Dwelling house combined with other uses 5. Store 6. Office 7. Inn and Hotel 8. Public facilities such as government building 9. Hospital and clinic 10. Day nursery 11. Factory 12. Warehouse 13. School 14. Gymnasium 15. Theater, amusement facilities 16. Others ()
4 Type of Structure 1. Reinforced concrete 2. Pre-cast concrete 3. Concrete block 4. Steel framed reinforced concrete 5. Hybrid of () and ()
5 Number of stories Above ground _____ and underground _____
6 Size of the building Dimensions of the first floor $\text{m} \times \text{m}$ _____

Inspection Inspection method (1. Appearance inspection only 2 Appearance and internal visual inspection)

Inspection 1 The degree of danger judged at a glance (mark the appropriate items with a circle, judge the building to be dangerous, stop the inspection and skip to the comprehensive judgment)

- | | |
|---|---|
| 1. Entire or partial collapse and fallen floors of the building | 2. Significant destruction of the foundation and its significant displacement from the superstructure |
| 3. Significant inclination of the building in whole or in part | 4. Others () |

Inspection 2 The degree of danger judged from the states of the adjacent buildings, the nearby ground, the building frames and other factors

Judgment (1)	Rank A	Rank B	Rank C
① Whether there are members that suffered damage severer than damage level III	1. No	<u>2</u> Yes	

Judgment (2)	Rank A	Rank B	Rank C
② Presence of danger caused by destruction of the adjacent buildings and the nearby ground	<u>1</u> No	2. Uncertain	3. Yes
③ Settlement of the entire building due to destruction of the ground	<u>2</u> Less than 0.2 m	2. 0.2 m - 1.0 m	3. More than 1.0 m
④ Inclination of the entire building due to differential settlement	<u>1</u> Less than 1/60	2. 1/60 - 1/30	3. More than 1/30

Damage to columns (the floor (which suffered the most serious damage) through the inspecting for ⑤ and ⑥ below (1)) (if bearing wall structure is in use, the length of the wall is substituted for the number of columns)

⑤ Number of columns that suffered damage level V (3) / Number of columns inspected (34)
[Inspection rate 8.8 %]

⑥ Number of columns that suffered damage level IV (3) / Number of columns inspected (34)
[Inspection rate (8.8 %)]

Judgment (2)	Rank A	Rank B	Rank C
⑤	1. Less than 1 %	2. 1 % - 10 %	3. More than 10 %
⑥	<u>1</u> Less than 10 %	2. 10 % - 20 %	3. More than 20 %
Judgment (2)	1. Inspected (when all items are given Rank A)	2. Limited entry (when one of the items is given Rank B)	3. Unsafe (when one or more items are given Rank C, or when two or more items are given Rank B)

Judgment of the degree of danger
Judgment is determined by judgment (1) or judgment (2), whichever is greater

1. Inspected (internal visual inspection required)	2. Limited entry	<u>3</u> Unsafe
--	------------------	-----------------

Inspection 3 The degree of danger caused by falling and shifting of objects

	Rank A	Rank B	Rank C
① Frame and glass of the window	1. Almost no damage	2. Deformation and cracks	<u>3</u> Danger of falling
② Exterior finishing material (for wet construction)	1. Almost no damage	2. Partial cracking and crevices	<u>3</u> Significant cracking and spalling
③ Exterior finishing material (for dry construction)	1. Slight damage such as cracks in the joint	2. Crevices observed in the plate	3. Significant displacement of the joint and destruction of the plate
④ Signboard and fitting	1. No tilt	2. A slight tilt	3. Danger of falling
⑤ Exterior escape stair	1. No tilt	2. A slight tilt	3. A significant tilt
⑥ Others ()	1. Safe	2. Special attention required	3. Dangerous
Judgment of the degree of danger	1. Inspected (when all items are given Rank A)	2. Limited entry (when one or more item is given Rank B)	<u>3</u> Unsafe (when one or more item is given Rank C)

Comprehensive judgment (the building should be judged here to be dangerous if it was judged to be dangerous in Inspection 1; otherwise it should be judged according to the degree of danger in Inspection 2 or in Inspection 3, whichever is greater).

1. Inspected (green) 2. Limited entry (yellow) 3. Unsafe (red)

Comment (state whether danger is from the building frame, or from falling objects)

Serial No. _____

Building No. _____

Serial No. in the residential district map _____

3 _____
4 _____
Above ground _____ stories
Under-ground _____ stories
a _____ m
b _____ m

Inspection method _____

1 _____

Judgment (1) _____

② _____

③ _____

④ _____

The most seriously damaged floor _____

⑤ _____

⑥ _____

Judgment (2) _____

Judgment _____

① _____

② _____

③ _____

④ _____

⑤ _____

Judgment _____

Comprehensive judgment _____



Seki M., UTCB Lecture note, May 2017, BRI, Japan

Training Video in Chile

Conclusions

1. Japan has already performed the seismic evaluation for the huge number of existing buildings such as RC, steel and timber structures.
2. For the public building, most of buildings are finished, but for the private office and residential building are still on the way.
3. Just after the earthquake, the quick inspection and more detail inspection and retrofit should be done immediately.

**Thank you for
your attention!**